



Reviewer Issues

7/11/12 10:03 am

THE CITY OF SAN DIEGO
Development Services
1222 First Avenue, San Diego, CA 92101-4154

L64A-002A

Page 1 of 1

Project Information

Project Nbr: 266825 **Title:** COPLEY - PRICE FAMILY YMCA
Project Mgr: Black, Laura (619) 236-6327 Lblack@sandiego.gov



Review Information

Cycle Type: 16 BDR-Geology (Submit)	Submitted: 06/27/2012	Deemed Complete on 06/27/2012
Reviewing Discipline: BDR-Geology	Cycle Distributed: 06/27/2012	
Reviewer: Thomas, Patrick (619) 446-5296	Assigned: 06/27/2012	
Hours of Review: 2.00	Started: 06/27/2012	
Next Review Method: Conditions	Review Due: 07/10/2012	
	Completed: 07/09/2012	COMPLETED ON TIME
	Closed: 07/10/2012	

Last month BDR-Geology performed 37 reviews, 100.0% were on-time, and 94.1% were on projects at less than < 3 complete submittals.

3rd Review/Cycle 16 References

<u>Cleared?</u>	<u>Issue Num</u>	<u>Issue Text</u>
<input checked="" type="checkbox"/>	1	Preliminary Geologic Reconnaissance and Geotechnical Evaluation, Copley Family YMCA, 4300 El Cajon Boulevard, San Diego, California; prepared by TerraCosta Consulting Group, Inc., dated June 25, 2012 (their project no. 2638A). Preliminary Grading and Drainage Plan, New Recreation Facility, Copley-Price Family YMCA, City Heights, PTS 242653, San Diego, California, prepared by REC Consultants, Inc., dated December 15, 2011. (New Issue)

3rd Review/Cycle 16 Comments

<u>Cleared?</u>	<u>Issue Num</u>	<u>Issue Text</u>
<input checked="" type="checkbox"/>	2	The referenced geotechnical documents have been reviewed. Based on that review, the geotechnical consultant has adequately addressed the soil and geologic conditions potentially affecting the proposed project for the purposes of environmental review. (New Issue)
<input checked="" type="checkbox"/>	3	The previously provided Geology Requirements for permit conditions remain applicable. (New Issue)

For questions regarding the 'BDR-Geology' review, please call Patrick Thomas at (619) 446-5296. Project Nbr: 266825 / Cycle: 16

